



Weekly Update

Sept 11 – 17

Repair Work

Devil's Slide (post mile 39.14)

- Excavation work got underway to provide temporary access for the work needed to extend the drain pipe below the road. This will allow all drain water to be discharged close to the ocean and eliminate the potential of erosion from this source.



Excavator and bulldozer at work to create access for drain the extension

- The slide movement sensor system was inspected by Caltrans Signal Operations group this week. A thorough inspection of sensors, wiring and electrical components was undertaken. Some components remain on backorder.



New emergency message sign and signals

Slide Location No. 3 (post mile 39.77)

- Excavating and lagging the last 7 feet of the retaining wall was completed this week. The steel beams were painted to blend in and match the wood lagging.



Partial excavation at the wall base



Compacting earth at the bottom of the wall